

essection in excession in the comment of the commen

OTIC FILE CUE



AD-A193 456



CLEANABILITY OF AIRCRAFT POLYURETHANE TOPCOATS

Charles R. Hegedus and Donald J. Hirst

Air Vehicle and Crew Systems Technology Department NAVAL AIR DEVELOPMENT CENTER Warminster, PA 18974-5000



JANUARY 1988

*Original contains color plates: All DTIC reproduct- two will be in black and while."

PHASE REPORT PROJECT NO. R534A52 WORK UNIT ZM 540

Approved for Public Release; Distribution Unlimited

Prepared for
NAVY EXPLORATORY DEVELOPMENT PROGRAM
AIRBORNE MATERIALS
(NA2A)
NAVAL AIR DEVELOPMENT CENTER
Warminster, PA 18974-5000

NOTICES

REPORT NUMBERING SYSTEM – The numbering of technical project reports issued by the Naval Air Development Center is arranged for specific identification purposes. Each number consists of the Center acronym, the calendar year in which the number was assigned, the sequence number of the report within the specific calendar year, and the official 2-digit correspondence code of the Command Office or the Functional Department responsible for the report. For example: Report No. NADC-86015-70 indicates the fifteenth Center report for the year 1986 and prepared by the Systems and Software Technology Department. The numerical codes are as follows:

CODE	OFFICE OR DEPARTMENT
00	Commander, Naval Air Development Center
01	Technical Director, Naval Air Development Center
02	Comptroller
05	Computer Department
07	Planning Assessment Resources Department
10	Anti-Submarine Warfare Systems Department
20	Tactical Air Systems Department
30	Battle Force Systems Department
40	Communication & Navigation Technology Department
50	Mission Avionics Technology Department
60	Air Vehicle & Crew Systems Technology Department
70	Systems & Software Technology Department
80	Engineering Support Group

PRODUCT ENDORSEMENT – The discussion or instructions concerning commercial products herein do not constitute an endorsement by the Government nor do they convey or imply the license or right to use such products.

APPROVED BY:

W. F. MORONEY

CAPT, MSC, U.S. NAVY

DATE: 15 July 88

JECORITY CEA	SSIFICATION O	i ini rade	REPORT DOCUM	AENITATION	DAGE	717	42 111
REPORT DOCUMENTATION PAGE μ 193 43				72 736			
1a. REPORT SECURITY CLASSIFICATION UNCLASSIFIED			16 RESTRICTIVE N/A	MARKINGS			
2a. SECURITY	CLASSIFICATIO	N AUTHORITY		3 DISTRIBUTION	/AVAILABILITY OF	REPORT	
26 DECLASSIF	ICATION / DOW	VNGRADING SCHEDU	LE	Approved for F Distribution Un	Public Release; nlimited		
4. PERFORMIN	G ORGANIZAT	ION REPORT NUMBE	R(S)	5. MONITORING	ORGANIZATION RE	PORT NUM	MBER(S)
NADC-87	164-60			N/A			
		ORGANIZATION	66 OFFICE SYMBOL	7a. NAME OF MO	ONITORING ORGAN	IZATION	
Naval Ai	r Developme	ent Center	(If applicable) 6062	N/A			
6c. ADDRESS	City, State, an	d ZIP Code)			ty, State, and ZIP C	ode)	
Warmins	ster, PA 1893	74-5000		N/A			
8a. NAME OF	FUNDING / SPC	NSORING	8b OFFICE SYMBOL	9. PROCUREMEN	T INSTRUMENT IDE	NTIFICATIO	ON NUMBER
ORGANIZA Navy Ex		iterials Program	(If applicable) 60C2	N/A	•		
8c. ADDREGS (City, State, and	ZIP Code)		10. SOURCE OF F	UNDING NUMBERS	5	
	r Developme			PROGRAM ELEMENT NO	PROJECT NO R5	TASK NO	WORK UNIT ACCESSION NO
Warmins	ster, PA 1897	74-5000		62234N	34A52	1	ZM540
11. TITLE (Incl	ude Security C	lassification)		<u> </u>		<u> </u>	· · · · · · · · · · · · · · · · · · ·
(U) Cle	anability of A	Aircraft Polyuretha	ne Topcoats				
12. PERSONAL	AUTHOR(S)						
		and Donald J. H	rst				
13a. TYPE OF Phase	REPORT	136 TIME CO		14. DATE OF REPO	PRT (Year, Month, E	Day) 15	PAGE COUNT
16. SUPPLEME	NTARY NOTAT	TION					
			(
17	COSATI	CODES	18 SUBJECT TERMS (e if necessary and	identify b	y block number)
FIELD	GROUP	SUB-GROUP	Polyurethane, Topcoat	Soil			
11	3		Cleanability	S			
19 ABSTRACT	(Continue on	reverse if necessary	and identify by block n				
~			craft are painted with		huo component	aliabatio	polyurathana
			e diisocyanate and a				
specifica	ation MIL-C-	83286. One defici	ency of this coating v	which is frequent	tly reported by fi	eld activi	ties is its poor
			d approximately ever				
constantly and cleaned approximately every two weeks. The gray lusterless topcoats used in the camouflage schemes often cannot be restored to their original color, even with standard aircraft cleaners. In addition, when the							
discolored topcoat is damaged and must be repaired, matching of the color is impossible for field touch-up.							
A test to evaluate coating cleanability has been utilized to determine the severity of this problem and							
recommend possible solutions. Several coatings on the MIL-C-83286 qualified products list were evaluated along							
with topcoats which contain polymer bead pigments. A distinct correlation was found between cleanability and 60°							
gloss. Topcoats with a gloss of less than 4 had significant color changes when soiled and cleaned; coatings with gloss values above 4 had color changes that were far less noticable even after 10 soiling/cleaning cycles. This							
_	TION / AVAILAB	ILITY OF ABSTRACT	RPT DTIC USERS	21 ABSTRACT SE	CURITY CLASSIFICA	ATION	Ken,
22a NAME O	F RESPONSIBLE	INDIVIDUAL		226 TELEPHONE	(Include Area Code)		ICE SYMBOL
Charles R. Hegedus and Donald J. Hirst 215-441-1452 6062							

DD FORM 1473, 84 MAR

83 APR edition may be used until exhausted All other editions are obsolete

SECURITY CLASSIFICATION OF THIS PAGE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE

BEET TO SECOND PERSONS OF THE PROPERTY FERENCES PROPERTY OF THE PROPERTY OF THE PERSONS OF THE P

19. Abstract (Continued)

effect is caused by the surface roughness required for low gloss coatings, which allows carbonaceous soil particulates to become entrapped in the coating surface. Coatings which were more hydrophilic, as determined by water contact angle, were more cleanable than those which were hydrophobic. This effect is attributed to the smoother surface of the hydrophilic coatings and the ability of the cleaner to wet these surfaces. It was also found that low gloss (\leq 3) topcoats containing polymer beads were more cleanable than their conventionally pigmented counterparts. Scanning electron micrographs comparing the surfaces, illustrated that this is due to less voids and more rounded surface protrusions in the polymer bead coatings. Coatings which are cleaned shortly after application and cure were found to be significantly more cleanable than non-cleaned coatings. The pre-cleaning makes the surface more hydrophilic and may smooth out some of the surface irregularities without increasing gloss.

UNCLASSIFIED

TABLE OF CONTENTS

	Page
LIST OF TABLES	ii
LIST OF FIGURES	ii
INTRODUCTION	1
BACKGROUND DISCUSSION ON COLOR	2
EXPERIMENTALS	3
RESULTS AND DISCUSSION	5
CONCLUSIONS	9
RECOMMENDATIONS	9
REFERENCES	9
ACKNOWLEDGEMENTS	10
APPENDIX A: COMPOSITION OF NADC SELF-PRIMING TOPCOAT	A-1
APPENDIX B: CLEANABILITY TEST FOR AIRCRAFT COATINGS	B-1

LIST OF TABLES

Table		Page
1	Polyurethane Topcoats Analyzed	4
II	Test Procedures	5
Ш	Polyurethane Topcoat Properties	6
IV	Comparison of Cleanability of Polymer Bead and Conventional Pigmented Topcoats	8
V	Cleanability and Water Contact Angle of Virgin and Pre-Cleaned Topcoats	9

LIST OF FIGURES

Figure		Page
1	Schematic of F/A-18 Multi-Theater Camouflage Scheme	11
2	Multi-Theater Camouflage Scheme Colors	12
3	L,a,b Color Graph	13
4	dE of Aircraft Polyurethane Topcoats After Cleanability Test	14
5	Clnorm Versus dE of Original Topcoats	15
6	Clnorm Versus dE for Polyurethane Topcoats	16
7	dE Versus Gloss for Original Topcoats	17
8	dE Versus Contact Angle for Original Topcoats	18
9	dE Versus Gloss for Polyurethane Topcoats	19
10	Scanning Electron Micrographs of Polyurethane Topcoats, 500X	20
11	Scanning Electron Micrographs of Polyurethane Topcoats, 2000X	21
12	dE Versus Soiling/Cleaning Cycles for Polyurethane Topcoats	22

PREFACE

Under the Navy Exploratory Development Program for Airborne Materials, a project was undertaken to study the cleanability and weatherability of camouflage coating systems. The following is a phase report which discusses the cleanability of aircraft polyurethane topcoats. Analysis of the weatherability of these coatings is ongoing and will be addressed in a future report.

During this project, commercially available coatings which qualify under military specifications were analyzed. The discussion of these products in this report does not imply or otherwise constitute an endorsement by the authors or the U.S. Government.

INTRODUCTION

Currently, Navy operational tactical aircraft are painted in multi-theater camouflage schemes designed to minimize optical detectability in a variety of world-wide engagement scenarios. These camouflage schemes normally consist of several shades of lusterless gray colors which closely match the aircraft's operational background visible reflectance and have a low specular reflectance. Figure 1 is a schematic of the F/A-18 camouflage scheme in the designated Federal Standard 595 colors. For comparison, Figure 2 illustrates the four shades of gray used in these schemes, along with white and black specimens.

Navy aircraft paint systems consist of an epoxy primer (MIL-P-23377 or MIL-P-85582) and a polyurethane topcoat (MIL-C-83286). The topcoat is a two component, aliphatic polyurethane which is the product of a polyester polyol and hexamethylene diisocyanate. Although this coating is chemical and weather resistant, two of the most significant problems encountered with aircraft paint systems are degradation of the coating and color change caused by ultraviolet radiation and carbonaceous soils. All organic coatings are susceptible to polymeric degradation caused by environmental exposure. UV radiation, high humidity, sea spray, and surface contaminants cause paints to crack, blister, debond, and change color. In addition, entrapped dirt can drastically change a coating's optical properties and even the most successful cleaners have been unable to restore these properties to these camouflage coatings. Degradation and color change of the paint system have several detrimental effects:

- (1) Corrosion of aircraft alloys, excluding mechanical damage, is significantly controlled by the integrity of the protective coating system (1).
- (2) Color change of the coating system may hinder the intended camouflage properties.
- (3) Matching topcoat colors during touch-up is difficult, making aircraft unsightly.

In order to minimize or eliminate these effects, this project was undertaken to:

(1) Determine and analyze the effects of weathering and soiling/cleaning on the camouflage aircraft polyurethane topcoat, MIL-C-83286.



ing/cleaning

[]

State to the state of the passes of the pass

A-1

- (2) Determine coating compositional, optical, mechanical, and surface properties which enhance weatherability and cleanability.
 - (3) Recommend possible formulation changes to improve coating performance.

This is a phase report which discusses the cleanability of aircraft polyurethane topcoats.

BACKGROUND DISCUSSION ON COLOR

One of the main objectives of this effort was to analyze changes in paints after soiling/cleaning. One such change is color. Although it is beyond the scope of this report to present details of color theory and principals, it is necessary to have a common basic knowledge of color and colorimetry. Color is defined as a psychological response to the physical stimulus of light, other than spatial and temporal inhomogeneities, by the retina of the eye (2). Colorimetry is the measurement and relative correlation of what is seen by the eye.

Color can be fully defined by three separate and distinct terms: lightness, hue, and saturation. Lightness is described as that characteristic of a color relating to the degree of whiteness/blackness. That is, the relative arrangement of the achromatic "lightness" characteristic of the color. For example, the lightness of achromatic grays is solely dependent on how dark they are. Hue is the attribute of a color by which it is perceived to be red, yellow, green, blue, purple, etc. White, black, and achromatic grays contain no hue. Saturation can be perceived as the pureness or deepness of a color. For example, fire engine red has a higher saturation than a dull, washed-out red. This description of color illustrates that three concepts or values are adequate to fully define a specific color.

There are several color order systems, the most common of which are the Munsell and the CIE systems. The Munsell system is a qualitative ordering of colors based on the above three concepts of lightness, hue, and chroma; it is a selection and ordering of various color samples as well as a physical description of these colors. The CIE system is a quantitative description of colors based on the concept that all colors can be obtained from the mixing of the three primary colors: red, green, and blue. These systems are fully described in the literature (3,4).

One modification of the CIE system is the L,a,b color coordinate system. It uses three numbers to quantify and define colors. Figure 3 is a graph illustrating how the three numbers are determined and represented. The L value is a measure of the lightness of the color where 0 is a pure black and 100 is a pure white. The "a" value is the red-green coordinate. When the value is positive, the sample is more red than green, whereas if it is negative, the sample is closer to a true green. The "b" value is the yellow-blue coordinate, negative values indicating a bluer color and positive values indicating a yellow color. By providing the L, a, and b values, a color is fully defined. One major advantage of this system, as illustrated in Figure 3, is the ease of perception of a given color from its Lab coordinates. This is especially true when describing or analyzing color differences. It is easier to invision a color difference when described as being whiter, bluer, redder, etc. Color

differences can be easily quantified by using these Lab coordinates. A dimensional difference, dE, on the color graph can be calculated by:

$$dE = \sqrt{(L_f - L_i)^2 + (a_f - a_i)^2 + (b_f - b_i)^2}$$
 (1)

where L, a, and b are tricoordinate color values, normally obtained from a colorimeter; i and f denote the L, a, and b values prior to and after exposure and/or conditioning, respectively.

It must be noted that although this approach provides a quantitative value for color differences, the exact accuracy of this magnitude is dependent upon a number of complicated factors which include the actual perception and acuity of the observer, the wavelengths and intensity of light, and geometric factors. In addition, colors with the same dE values when compared to a standard can be extremely different. For example, one color may be lighter than the standard, thus having a higher L value, while another color may be the same lightness but much redder. The result may be the same dE with the two sample colors being totally different. Nonetheless, the importance of the above discussion is that the tricoordinate Lab system provides a quantitative description of colors and color differences with a consistent meaning in terms of visual perception. It has been stated that the average naked human eye can, in general, discern color differences with a dE greater than 1. Although this generalization does not indicate what is acceptable, it provides a base line for understanding the magnitude of how color differences are perceived.

EXPERIMENTAL

Materials

Table I is a list of the polyurethane topcoats analyzed during this investigation. Deft and DeSoto coatings are on the MIL-C-83286 qualified products list and, as such, are used extensively on Navy aircraft. The Camolite coating is similar to the MIL-C-83286, however it contains polymeric bead pigments. It is used as the finish coat on production F/A-18 aircraft and is specifically formulated with the beads to improve cleanability of the coating. The self-priming topcoat is an NADC developed material designed to replace the conventional primer and topcoat system. The formulation is listed in Appendix A and the material is further described in reference (5). The materials tested were primarily Federal Standard 595 colors: 35237, 36320, 36375, and 36495. In addition, several of these coatings were modified in-house to vary their gloss properties.

Specimens were prepared by applying 0.6 to 0.9 mils (15.2 to 22.9 μ m) of MIL-P-23377D epoxy primer to 2024 T-3 bare aluminum specimens which were cleaned and chromated with materials conforming to MIL-C-81706 to produce a chemical conversion coating meeting MIL-C-5541. The impact flexibility test specimens were 2024-0 temper aluminum alloy, anodized in accordance with MIL-A-8625, Type 1. The dimensions of all specimens were 3 x 6 x 0.02 inches (7.62 x 15.24 x 0.05 cm). The two-component topcoats were prepared by mixing the components and allowing a 30 minute dwell time before application. The coatings were then applied to a dry film thickness of 2.0 + 0.2 mils (50.8 + 5.1 μ m). The self-

priming topcoat was applied directly to the metal surface without the use of a primer. The coatings were allowed to cure at ambient laboratory conditions for two weeks prior to testing. The dwell and cure times were selected after a preliminary testing program indicated that these times would provide consistant and realistic results.

Table I: POLYURETHANE TOPCOATS ANALYZED

MANUFACTURER	MANUFACTURER'S CODE	FED. STD. 595 COLOR
Deft	03-B2-73/03-BL-73	35237
Deft	03-GY-97/03-GY-97	36320
Deft	03-GY-98/03-GY-98	36375
Deft	03-GY-214/03-GY-214	36495
De Soto	826x377/910x376	35237
De Soto	822x362/910x376	36320
De Soto	822x363/910x376	36375
De Soto (CAMOLITE)	822x542/910x665	36320
De Soto (CAMOLITE)	822x544/910x665	36375
NADC	UB-14, Self-Priming Topo	oat 35237

Test Procedures

THE REPORT OF THE PERSON OF TH

The cleanability test was a modification of a proposed ASTM method devised to evaluate the cleaning efficiency of aircraft surface cleaners (6). Modifications to the procedure were made because the original method was devised to evaluate the efficiency of cleaners while the desired test in this study was for cleanability of coatings. The modified procedure is described in detail in Appendix B. This method has provided consistent and representative results relative to actual field experience. The soil was selected based on previous studies (7,8) which have indicated this soil to be representative of that found on operational aircraft.

Hardness, flexibility, color, and gloss of untreated and soiled/cleaned coatings were measured according to the procedures listed in Table II. The procedures used to determine film hardness were modifications of the listed ASTM methods. Although these methods were originally designed to test coating adhesion, they were modified slightly in this study to quantify and analyze film hardness. The modifications involved determination of the weight needed to scratch and mar the surface of the film.

Color values were measured using a MacBeth 1010S colorimeter. The color change due to soiling and cleaning was quantified using the dE value (equation 1) calculated prior to and after conditioning. In order to compare cleanability effects of different colors and since the soil was black and it primarily affected the L value, a normalized cleanability value, CLNORM, was calculated:

$$CLNORM = L_F/L_f$$

where L_i and L_f are the L values prior to and after cleaning.

Table II: TEST PROCEDURES

PROPERTY	PROCEDURE
Gloss, 60°	ASTM D 523
Color	ASTM D 2244
Adhesion (Hardness)	
Scrape	ASTM D2197 A
Microknife	ASTM D2197 B
Impact Flexibility	
G.E.	FTMS 141, 6226
Gardner	ASTM D2794

60 and 85 degree gloss values were according to ASTM D523 measured using a Glossgard II manufactured by Pacific Scientific. Although both 60° and 85° glosses are recommended for semi- and low-gloss finishes (9), 60 degree measurements are more commonly used for aircraft coatings. 85 degree measurements are used for low gloss materials to describe their sheen properties. During this investigation, the best correlations were found between 60 degree gloss values and cleanability. Unless otherwise stated, all gloss values are for 60 degree geometry. 85 degree gloss values were periodically measured to determine effects on camouflage properties which require low sheen.

The contact angle, θ , of distilled water on the coatings' surface was measured at 70° F (21° C) and 50% relative humidity using a Rame-Hart contact angle goniometer, model 100.

CHANGE TO PROPERTY OF STATES OF STAT

RESULTS AND DISCUSSION

Physical, optical, and surface properties of the 10 coatings tested are listed in Table III along with dE and CLNORM values obtained after the cleanability test. As illustrated in Figure 4, dE values for the materials tested range from 1.7, which is a barely noticeable color change, to 16.3, which is a drastic color change. This indicates that soiling of camouflage aircraft surfaces, even when cleaned with a standard aircraft cleaner, may cause significantly noticeable color changes. CLNORM was calculated to normalize the differences between colors in order to compare the cleanability of the various color coatings. However, in comparing CLNORM and dE (See Figure 5) for the 10 original coatings, there is a direct linear relationship. This relationship was confirmed by comparing dE and CLNORM (See Figure 6) for additional coatings evaluated during this study which are described later. Therefore, direct comparison of dE between coatings is valid.

Although no correlation could be found between impact flexibility or hardness with dE, gloss and contact angle had distinct effects on cleanability. Figures 7 and 8 illustrate dE versus gloss and contact angle, respectively. Figure 7 indicates an increase in dE, poor cleanability, as gloss is decreased. This is especially evident at low gloss values. In order to further quantify the effects of gloss on cleanability, the conventionally pigmented coatings listed in Table II (those not containing polymer beads) were modified to increase their gloss to varying degrees by adding clear isocyanate and polyester polyol resins to their formulations to increase polymer binder concentration,

TABLE III. POLYURETHANE TOPCOAT PROPERTIES

(DEGREES)	8	92	74	86	18	25	8	85	28	۲۲
GL055	1.6	3.6	5.2	1.1	1.1	5.0	1.2	1.2	6.1	4. 8
SCRAPE (KGS)	250	1000	200	1000	250	250	200	250	1000	250
HICRO (GRPHS)	300	400	300	300	300	320	400	250	320	100
GARDNER (IN-LB)	65	30	20	ហ	75	80	w	80	80	15
6.E. (2 ELDRG)	9	20	9	10	9	9	ហ	3	9	8
띪	4.51	2,35	1.23	13.07	9.73	1.70	16.31	11.29	1.87	6.20
CLNORM	91.9	96.0	98.4	76.5	83.3	97.9	73.1	81.7	96.5	90.3
CORTING	DEFT, 35237	065010, 35237	DEFT, 36320	DESOTO, 36320	CRMOLITE, 36320	DEFT, 36375	DESOTO, 36375	CRMOLITE, 36375	DEFT, 36495	NADC, PR/PC

decrease pigment concentration, and thus increase gloss. Figure 9 is a graph illustrating a wide range of gloss versus dE. The insert in the upper right hand corner clearly illustrates a critical gloss of approximately 4.0, below which the coatings drastically change color when soiled and cleaned. Difference in surface roughness is illustrated in scanning electron micrographs at 500X and 2000X in Figures 10 and 11, respectively. Figures 10a and 11a are Deft 36320 with a gloss of 5.7 and a dE of 1.23. Figures 10b and 11b are DeSoto 36320 with a gloss of 1.1 and dE of 13.07; Figures 10c and 11c are Camolite 36320 with a gloss of 1.1 and dE of 9.73. The gloss/dE relationship is easily explained considering that reduction in gloss is caused by increasing the surface roughness. The increased surface roughness can entrap carbonacious particles which have a diameter of approximately 0.02 microns. Coatings with gloss values above 4 change color only slightly. Although "low" gloss coatings are required for camouflage purposes, it may be possible to have gloss requirements of between 4 and 7 to maintain camouflage properties while having a more cleanable and maintainable coating system.

Although it is difficult to mathematically describe the relationship between the contact angle of water and the dE obtained after cleanability (Figure 8), it is obvious that coatings with lower contact angle are more cleanable. It should be noted that lower water contact angles indicate the coating surface is more hydrophilic. This agrees with results from a previous study (7). In addition, rougher surfaces can often produce higher contact angles due to the geometry at the coating surface/water droplet interface. Therefore, coatings with lower water contact angles may be more cleanable for two reasons: (1) The cleaner can wet the hydrophilic surface and thus be more effective and/or (2) a smoother surface allows less dirt particulates to be entrapped.

TOTATE NO SELVE DE L'ELECTE DE L'ESTE DE

The cleanability data of the original 10 topcoats (Table III and Figure 4) indicates that the Camolite coatings which contain polymer beads are more cleanable than the DeSoto conventionally pigmented coatings, even though they both have similar gloss values. For example, both 36320 coatings have gloss values of 1.1 with dE values of 9.73 and 13.07, respectively. Figures 10 and 11 illustrate that coatings with polymer beads have a smoother surface than the conventionally pigmented coatings with equivalent gloss. The polymer bead coating has surface irregularities which are rounded and somewhat uniform while the conventionally pigmented material appears more resin starved with voids in the surface where dirt can be entrapped. As noted earlier, the polymer bead material is manufactured specifically to improve cleanability. Other reports (10, 11, 12) also have claimed polymer bead aircraft topcoats are more cleanable than conventionally pigmented counterparts. In order to further study the polymer bead effect, both 36320 topcoats were modified to increase their gloss by adding clear resin to their formulations. The cleanability of these coatings was measured and Table IV compares the dE/gloss relationship. As this table indicates the polymer bead effect decreases as gloss increases. At a gloss of 3 and above, the effect is no longer prevalent.

The results presented and discussed above are on aircraft camouflage topcoats which have been soiled and cleaned once. Operational aircraft are normally re-painted approximately every 3 to 4 years and throughout this time period, they are continuously soiled and periodically cleaned (usually every 2 weeks). In order to simulate this condition, Deft, DeSoto, and Camolite 36320 coatings were soiled and cleaned for 10 cycles. In addition, other specimens of

these coatings were cleaned without soiling to determine if the cleaner or cleaning action had an effect on color change. The dE values were calculated after each cycle using the original Lab color values. The specimens which were cleaned without soiling had de's of less than 0.55 after 10 cleanings, indicating that neither cleaner nor cleaning action had a significant effect on color change. Figure 12 illustrates the dE values for the 3 coatings after each soiling/cleaning cycle. The original gloss values of these coatings were 3.6, 1.2, and 1.3 for the Deft, DeSoto, and Camolite coatings, respectively. gloss difference explains the better cleanability of the Deft coating over the other two, which is evident throughout the 10 soiling/cleaning cycles. Also, the Camolite coating, with polymer bead pigment, performed better than the DeSoto coating even though they both have equivalent gloss characteristics. At the end of the tenth cycle, the dE values were 7.08, 18.75, and 23.43, respectively. The de's of the two low gloss coatings are extremely high and indicate drastic color changes. Although 7.08 indicates a noticeable color change, considering the 10 soiling and cleaning cycles, this may be acceptable; however, a color match of this coating during touch-up would be unlikely. It should be noted that for all three coatings, there was no significant change in either 60 or 85 degree gloss after the 10 soiling/cleaning cycles. In addition, SEMs at 500% and 2000% of these coatings showed no visual difference from the original surface.

Table IV: COMPARISON OF CLEANABILITY OF POLYMER BEAD AND CONVENTIONAL PIGMENT TOPCOATS

	dЕ	
GLOSS	CONVENTIONAL	POLYMER BEAD
1.1	13.07	9.73
2.8	4.63	
3.1		4.42
15.6		1.39
37.6	0.69	

The results indicate that surface topography and hydrophilicity have the most significant effects on coating cleanability. In an attempt to improve cleanability without effecting the gloss properties, the specimens which were cleaned without soil for 10 cycles were soiled and cleaned. It was believed that the cleaning action burnished the coating surface, making it smoother, without effecting the gloss. As indicated above, the gloss of the coatings did not change after the 10 cycles. The cleaning action also renders the coating surface more hydrophilic. Table V compares the cleanability of the virgin topcoats versus those that had been cleaned 10 times prior to soiling, along with the contact angle of water on these specimens. These results clearly indicate that the pre-cleaned specimens are more hydrophilic and more cleanable than the untreated, virgin topcoats. Therefore, pre-cleaning of aircraft after painting and prior to use may improve overall cleanability of the paint system. It should be noted from this data, that hydrophilic nature is not the sole criterion of cleanability. O for the untreated Deft coating is 740 with a resulting dE of 2.09 while 0 for the pre-cleaned Camolite is 720 with a dE of 6.13. Therefore, it is equally important to have a smoother surface, as well as a more hydrophilic surface.

Table V: CLEANABILTIY OF PRE-CLEANED AND VIRGIN TOPCOATS

TOPCOAT	VIR	PRE-CLEANED		
	dE	<u> </u>	<u>dE</u>	9
DEFT	2.09	74	1.32	62
DESOTO	14.67	98	10.53	83
CAMOLITE	9.71	81	6.13	72

CONCLUSIONS

- 1. Soiling of aircraft camouflage coatings causes significant color changes even after cleaning with a standard aircraft cleaner.
- 2. Gloss has a significant effect on cleanability. Coatings with a 60° gloss of less than 4 have drastic color changes when soiled and cleaned. This effect is magnified when the coatings are repeatedly soiled and cleaned.

- 3. The more hydrophilic a surface is, the more cleanable it will be.
- 4. Low gloss (≤ 3) polymer bead coatings are more cleanable than their conventionally pigmented counterparts.
- 5. Coating surfaces which are cleaned after coating application and prior to soiling are more hydrophilic and more cleanable.

RECOMMENDATIONS

- 1. Aircraft camouflage topcoats 60^0 gloss requirements should be between 4 and 7 to produce cleanable coating systems if survivability requirements do not dictate that this will detrimentally affect the mission of the aircraft.
- 2. Aircraft should be cleaned one or two days after paint system application to improve cleanability of the coating system.
- 3. If low gloss (≤ 3) must be utilized, polymer bead coatings should be applied because of their improved cleanability over conventionally pigmented coatings.


REFERENCES

- (1) R. N. Miller, "PREDICTIVE CORROSION MODELING PHASE I/TASK II SUMMARY REPORT", Lockheed-Georgia Company, Marietta, GA, Air Force Wright Aeronautical Laboratories Report AFWAL-TR-87-4068, August 1987.
- (2) Committee on Colorimetry, Optical Society of America, THE SCIENCE OF COLOR, New York, 1953.

- (3) F. W. Billmeyer, Jr. and M. Saltzman, PRINCIPLES OF COLOR TECHNOLOGY, Interscience Publishers, New York, 1966.
- (4) R. M. Johnston, "COLOR THEORY", PIGMENT HANDBOOK VOLUME III, T. C. Patton, ed., Wiley Interscience Publication, 1973.
- (5) C. R. Hegedus, "DEVELOPMENT OF A PRIMER/TOPCOAT AND FLEXIBLE PRIMER FOR ALUMINUM", Naval Air Development Center Report NADC-87016-60, Warminster, PA, 20 March 1987.
- (6) K. G. Clark, "CLEANING COMPOUND EFFICIENCY TEST METHOD FOR AIRCRAFT SURFACE CLEANERS", Naval Air Development Center Report NAD-84002-60, 22 Nov 1983.
- (7) R.H. Kissinger and C. A. Rader, "STUDIES OF SOIL/AIRCRAFT SURFACE/CLEANER INTERACTIONS TO PROVIDE A BASIS FOR IMPROVED CLEANER TESTING", The Gillette Company Research Institute, Rockville, MD, Naval Air Systems Command Contract N00019-71-C-0228, Jan 1972.
- (8) E. J. Jankowsky, S. J. Ketcham, and V. S. Agarwala, "AIRCRAFT CARRIER EXPOSURE TESTS OF ALUMINUM ALLOYS", Naval Air Development Center Report NADC-79251-60, 1 Nov 1979.
- (9) M.P. Morse, "SURFACE APPEARANCE", PIGMENT HANDBOOK VOLUME III, T. C. Patton, ed., Wiley Interscience Publication, 1973.
- (10) G. P. Bierwagen, et.al., "DURABLE, CLEANBLE COATINGS, PART I", Air Force Wright Aeronautical Laboratories Report AFWAL-TR-80-4148, Sept 1980.
- (11) G. P. Bierwagen, et.al., "DURABLE, CLEANABLE COATINGS, PART II", AFWAL-TR-4148, 1982.
- (12) G. P. Bierwagen, et.al., "DURABLE, CLEANABLE COATINGS, PART III", AFWAL-TR-4148, Oct. 1983.

ACKNOWLE DGEMENT

The authors wish to thank Mr. Dave Gauntt for performing the cleanability tests and providing essential observations and comments. The authors also wish to thank Mr. Ken Clark for his enlightening discussions throughout this effort.



ssessos percessa percessa posterios productions posterios percessa portecessa posterios produces posterios de

Figure 1 Schematic of F/A-18 Multi-Theater Camouflage Scheme

prost expenses in exercise subjects to interprete ex

Figure 2 Multi-Theater Camouflage Scheme Colors

L,a,b, COLOR SOLID

THE PERSONAL PROPERTY OF THE PERSONAL PROPERTY




Figure 3 L,a,b Color Graph

STATES OF THE PROPERTY OF THE






Figure 4 dE of Aircraft Polyurethane Topcoats After Cleanability Test

KKKO KIIKOSA TKEKKOOL SZIGGO, POZEKOTINKOOLOGINSKISTORISTIKISTORISTIKSSISTORISTIKSSISTORISTIKSSISTORISTIKSI



SECECCE DESISTANT RESECTOR ESSECTINGESTAND INVOLUNITIES SECUES IN EXECUTAR DESCENSE DESCENSE INSCRESS IN THE CONTRACT IN THE C

Figure 5



16





Figure 7 dE Versus Gloss for Original Topcoats

17









Figure 9 dE Versus Gloss for Polyurethane Topcoats





S



DEFT, 36320

DESOTO, 36320 8

 \Box

CAMOLITE, 36320

Scanning Electron Micrographs of Polyurethane Topcoats, 500X Figure 10

NOTIFIED TO POSSO DE LA COCCO LA LA COCCO LA COC

Principal pressor previous process





A: DEFT, 36320

3: DESOTO, 36320

S

C: CAMOLITE, 36320



Figure 11 Scanning Electron Micrographs of Polyurethane Topcoats, 2000X

SASSALAS (CONTROLLASSAS OF SASSAS (CONTRACTORS (CONTRACTORS (CONTRACTORS (CONTRACTORS CONTRACTORS)))

Province Research




Figure 12 dE Versus Soiling/Cleaning Cycles for Polyurethane Topcoats

APPENDIX A: COMPOSITION OF NADC SELF-PRIMING TOPCOAT

COMPONENT A	PERCENT BY WEIGHT
Polyester Polyol Resin Solution (1) Titanium Dioxide (2)	37.8 1.1
Titanium Dioxide Vesiculated Beads (3)	0.4 17.1
Zinc Phosphate (4) Organo-Zinc Salt (5)	1.7
Zinc Molybdate (6) Carbon Black (7)	30.1 trace
COMPONENT B	
Hexamethylene Diisocyanate Resin Solution (1)	11.8

These materials are mixed approximately 4 parts of Component A to 1 part of Component B, by volume.

- (1) Coatings for Industry, Inc., Souderton, PA (Urethabond X3009 A and B)
- (2) E. I. DuPont DeNemours and Company, Wilmington, DE (Ti-Pure R-960)
- (3) Enterprise Chemicals, Chicago, IL (Spindrift 20929)
- (4) Mineral Pigments Corp., Beltsville, MD (Phos-Plus J0866)
- (5) BASF, Holland, MI (Sicorin RZ)

(6) Sherwin-Williams, Chicago, IL (Moly-White 101)

APPENDIX B: CLEANABILITY TEST FOR AIRCRAFT COATINGS

This method is a laboratory procedure for determining the cleanability of an aircraft coating. It is a modification of a proposed ASTM method for evaluating the cleaning efficiency of aircraft exterior surface cleaners which is described in detail in reference (6). The soil listed in the procedure below was generated using a hydraulic fluid. This soil is representative of that found on fleet operational aircraft as discussed in references (7) and (8). Other soils can be derived from greases and lubricating oils.

1.0 Apparatus

1.1 Test panels $3 \times 6 \times 0.02$ inches (7.62 x 15.24 x 0.05 cm), cut from 2024 T3 aluminum alloy chromate conversion coated with materials conforming to MIL-C-81706 to produce a coating meeting MIL-C-5541.

ACCURACION DE PRESENTA MICROCOCOCAMINACIONA (MICROCOCAMINA DE PORTO DE LA PORTECIONA MICROCOCAMINA DE PORTO DE

- 1.2 One-quart (1 L), wide mouth, glass glass jars
- 1.3 Balance, accurate to 0.1 g
- 1.4 High shear mixer
- 1.5 Hog bristle brush (Gardner WG-2000-B)
- 1.6 Acid brushes
- 1.7 Rubber roller, 5.0 ± 0.1 pounds (2270 ± 50 grams)
- 1.8 Forced draft oven capable of $221^{\circ}F + 4 (105^{\circ}C + 2)$.
- 1.9 Wear tester (Gardner Heavy Duty Wear Tester)
- 1.10 Template for positioning panels on the wear tester (See Figure A-1)
- 1.11 Cellulose sponge backed with nylon web (Scotch Brite 63).
- 2.0 Preparation of Soil
- 2.1 Place 50.0 ± 0.5 grams of carbon black (such as Raven 1040 manufactured by Columbian Chemical Company) and 500 ± 1 gram of MIL-H-83282 hydraulic fluid.
- 2.2 Homogenize the mixture from 2.1 using a high shear mixer for 15 ± 1 minute. Prior to application of the soil to the test specimen, thoroughly stir or shake the mixture.
- 3.0 Preparation of the Control Formula Cleaner
- 3.1 The following is a control formula for MIL-C-85570, Type II aircraft cleaner as listed in paragraph 4.6.13.1 of the specification.
- 3.2 Mix the first five ingredients listed below, then neutralize the mixture to a pH of $\theta.\emptyset$ with acetic acid. Mix the last two ingredients together and then add that to the initial mixture.

Igepal CO-630 (1)	10.0 grams
Monamid 150 CW (2)	5.0
Dipropylene glycol methyl ether	10.0
Deionized water	71.5
Benzotiazole	0.5
Hostacor 2098 (3)	2.0
Morphaline	1.0

- (1) GAF Corporation or equivalent
- (2) Mona INdustries, Inc. or equivalent
- (3) American Hoechst Corp. or equivalent
- 4.0 Preparation of Test Panels
- 4.1 To the aluminum test specimens described in 1.1, apply MIL-P-23377 epoxy primer to a thickness of 0.6 to 0.9 mils (15.2 to 22.9 \(\mu\) m). Allow to dry for 1 hour at ambient laboratory conditions. Apply the desired topcoat to the intended thickness. For MIL-C-83286 polyurethane, mix the two components and allow a 30 minute dwell time. Apply MIL-C-83286 to a thickness from 1.8 to 2.2 mils (45.7 to 55.9 \(\mu\) m). Allow the coating to cure under the appropriate conditions, 2 weeks at ambient laboratory conditions for MIL-C-83286.
- 4.2 After allowing the desired cure time and conditions, use a bristle acid brush to coat the painted surface of a test panel with the soil described in 2.0. Remove excess soil by covering the test panel surface with absorbent tissue and exerting pressure by rolling the tissue with the 5 pound roller. Repeat this blotting three times using fresh tissue each time. Brush the soiled surface 10 times in one direction only, parallel to the long dimension of the test panel, using the hog bristle brush. Bake the test panel at 221 f \pm 4 (105 C \pm 2) for 60 \pm 1 minute.

AND REPORTED THE PROPERTY OF T

- 4.3 Measure the L, a, and b tristimulus values on a suitable colorimeter and record the values as L_i , a_i , and b_i , respectively.
- 5.0 Cleaning Procedure
- 5.1 Dilute the control cleaner by 1 part cleaner with 9 parts distilled water (by volume).
- Clean the test panel within 4 hours using the wear tester as follows. Cut the sponge with any texture "ribs" running perpendicular to the cleaning stroke and the dimension parallel to the cleaning stroke is 3.5 inches (90 mm) and the width is 2.75 inches (70 mm). When the dry sponge is attached to the cleaning head of the wear tester, the combined weight shall be between 1350 and 1400 grams. (Note: Use Velcro type strips on the cleaning head to attach the nylon web side of the sponge). Place soiled test panel in the template at 45 to the cleaning stroke (see Figure A-1). Saturate the sponge and cover the test panel with the diluted cleaner. After 55 to 65 seconds, clean the test panel using 5 cycles (10 strokes) of the wear tester, then immediately turn the test panel 90 in the template and clean for an additional 5 cycles. Rince the test panel under a flowing stream of tap water at room temperature and allow to fully dry. Perform at least 3

replicates for each coating.

- 5.3 Measure the L, a, and b values on the same colorimeter used in 4.3 and record them as L_f , a_f , and b_f , respectively.
- 5.4 Calculate the change in color due to soiling and cleaning according to:

$$dE = \sqrt{(L_f - L_i)^2 + (a_f - a_i)^2 + (b_f - b_i)^2}$$

5.5 A minimum of 3 replicates were tested for each coating at each condition.

APPENDIX B: CLEANABILITY TEST FOR AIRCRAFT COATINGS

This method is a laboratory procedure for determining the cleanability of an aircraft coating. It is a modification of a proposed ASTM method for evaluating the cleaning efficiency of aircraft exterior surface cleaners which is described in detail in reference (6). The soil listed in the procedure below was generated using a hydraulic fluid. This soil is representative of that found on fleet operational aircraft as discussed in references (7) and (8). Other soils can be derived from greases and lubricating oils.

- 1.0 Apparatus
- 1.1 Test panels $3 \times 6 \times 0.02$ inches (7.62 x 15.24 x 0.05 cm), cut from 2024 T3 aluminum alloy chromate conversion coated with materials conforming to MIL-C-81706 to produce a coating meeting MIL-C-5541.
- 1.2 One-quart (1 L), wide mouth, glass glass jars
- 1.3 Balance, accurate to 0.1 g
- 1.4 High shear mixer
- 1.5 Hog bristle brush (Gardner WG-2000-B)
- 1.6 Acid brushes
- 1.7 Rubber roller, 5.0 + 0.1 pounds (2270 + 50 grams)
- 1.8 Forced draft oven capable of $221^{\circ}F + 4 (105^{\circ}C + 2)$.
- 1.9 Wear tester (Gardner Heavy Duty Wear Tester)
- 1.10 Template for positioning panels on the wear tester (See Figure A-1)
- 1.11 Cellulose sponge backed with nylon web (Scotch Brite 63).
- 2.0 Preparation of Soil
- 2.1 Place 50.0 ± 0.5 grams of carbon black (such as Raven 1040 manufactured by Columbian Chemical Company) and 500 ± 1 gram of MIL-H-83282 hydraulic fluid.
- 2.2 Homogenize the mixture from 2.1 using a high shear mixer for 15 + 1 minute. Prior to application of the soil to the test specimen, thoroughly stir or shake the mixture.
- 3.0 Preparation of the Control Formula Cleaner

- 3.1 The following is a control formula for MIL-C-85570, Type II aircraft cleaner as listed in paragraph 4.6.13.1 of the specification.
- 3.2 Mix the first five ingredients listed below, then neutralize the mixture to a pH of 8.0 with acetic acid. Mix the last two ingredients together and then add that to the initial mixture.

Igepal CO-630 (1)	10.0 grams
Monamid 150 CW (2)	5.0
Dipropylene glycol methyl ether	10.0
Deionized water	71.5
Benzotiazole	0.5
Hostacor 2098 (3)	2.0
Morphaline	1.0

- (1) GAF Corporation or equivalent
- (2) Mona INdustries, Inc. or equivalent
- (3) American Hoechst Corp. or equivalent
- 4.0 Preparation of Test Panels
- 4.1 To the aluminum test specimens described in 1.1, apply MIL-P-23377 epoxy primer to a thickness of 0.6 to 0.9 mils (15.2 to 22.9 /m). Allow to dry for 1 hour at ambient laboratory conditions. Apply the desired topcoat to the intended thickness. For MIL-C-83286 polyurethane, mix the two components and allow a 30 minute dwell time. Apply MIL-C-83286 to a thickness from 1.8 to 2.2 mils (45.7 to 55.9 /m). Allow the coating to cure under the appropriate conditions, 2 weeks at ambient laboratory conditions for MIL-C-83286.
- 4.2 After allowing the desired cure time and conditions, use a bristle acid brush to coat the painted surface of a test panel with the soil described in 2.0. Remove excess soil by covering the test panel surface with absorbent tissue and exerting pressure by rolling the tissue with the 5 pound roller. Repeat this blotting three times using fresh tissue each time. Brush the soiled surface 10 times in one direction only, parallel to the long dimension of the test panel, using the hog bristle brush. Bake the test panel at $221^{\circ}f + 4$ $(105^{\circ}C + 2)$ for 60 + 1 minute.

- 4.3 Measure the L, a, and b tristimulus values on a suitable colorimeter and record the values as L_i , a_i , and b_i , respectively.
- 5.0 Cleaning Procedure
- 5.1 Dilute the control cleaner by 1 part cleaner with 9 parts distilled water (by volume).
- Cut the sponge with any texture "ribs" running perpendicular to the cleaning stroke and the dimension parallel to the cleaning stroke is 3.5 inches (90 mm) and the width is 2.75 inches (70 mm). When the dry sponge is attached to the cleaning head of the wear tester, the combined weight shall be between 1350 and 1400 grams. (Note: Use Velcro type strips on the cleaning head to attach the nylon web side of the sponge). Place soiled test panel in the template at 45° to the cleaning stroke (see Figure A-1). Saturate the sponge and cover the test panel with the diluted cleaner. After 55 to 65 seconds, clean the test panel using 5 cycles (10 strokes) of the wear tester, then immediately turn the test panel 90° in the template and clean for an additional 5 cycles. Rince the test panel under a flowing stream of tap water at room temperature and allow to fully dry. Perform at least 3

replicates for each coating.

COSCIONAD INCOCOCCA INCOCANA I

- 5.3 Measure the L, a, and b values on the same colorimeter used in 4.3 and record them as L_f , a_f , and b_f , respectively.
- 5.4 Calculate the change in color due to soiling and cleaning according to:

$$dE = \sqrt{(L_f - L_i)^2 + (a_f - a_i)^2 + (b_f - b_i)^2}$$

5.5 A minimum of 3 replicates were tested for each coating at each condition.

Rockwell International Attn: L.Streett, Dept. 871	1
4300 E. 5TH Ave.	
Columbus, OH 43216	
Columbus, on 43210	
Sherwin Williams	1
Attn: G. Bierwagon	
10909 S. Cottage Grove Ave.	
Chicago, IL 60628	
Sterling Laquer	1
Attn: G. Halet	
3150 Brannon Ave.	
St. Louis, MO 63139	
Titanine Div	1
Attn: C. Scaturo	
320 Paterson Plank Rd.	
Carlstadt, NJ 07072	
U.S. Paints	1
Attn: J. Lott	
831 S. 21ST St.	
St. Louis, MO 63103	
Warner-Robbins Air Logistics Command (MMEMC, MMTRC)	2
Robbins AFB, GA 31098	
Wright Aeronautical Laboratories (MLSA)	1
Wright-Patterson AFB, OH 45433-6533	
NAME AND THE PROPERTY OF THE COOK OF THE C	84
NAVAIRDEVCEN (80 for 6062. 3 for 8131. 1 for 60C2)	04

ACCESSED TO THE TOTAL OF THE CONTRACT OF THE PARTY OF THE

Naval Aviation Depot (342) Naval Air Station Alameda, CA 94501	1
Naval Aviation Depot (343) Naval Air Station	1
Jacksonville, FL 32212-0016 Naval Aviation Depot (343) Naval Air Station	1
Norfolk, VA 23511-5188 Naval Aviation Depot (342)	1
Naval Air Station Pensacola, FL 32508	1
Naval Aviation Depot (34210) Naval Air Station, North Island San Diego, CA 92135-5100	1
Naval Civil Engineering Laboratory (L52) Port Hueneme, CA 93043	1
Naval Facilities Engineering Command (032) 200 Stovall Street Alexandria, VA 22332-2300	1
Naval Research Laboratory (6120, 6123, 6124) 4555 Overlook Avenue Washington, DC 20375	3
Naval Sea Systems Command (SEA-05M1) Washington, DC 20362	1
Office of Naval Research (431, 12) 800 North Quincy Street Arlington, VA 22217-5000	2
Office of Naval Technology (ONT-225) 800 North Quincy Street Arlington, VA 22217-5000	1
Pfizer Inc. Attn: D. Towhill 640 N. 13TH St.	ı
Easton, PA 18042 Pratt and Lambert	
Attn: S. Mack 16116 E. 13TH St. Wickita, KS 67201	1

SSSSSS TOTAL

Koppers Inc.	1
Attn: F. Winkelman	
480 Frelinghuysen Ave.	
Newark, NJ 07114	
Lehigh University (H. Leidheiser)	1
Bethlehem, PA 18015	
	_
Lenmar Inc.	1
Attn: M. Sandler	
150 S. Calverton Rd.	
Baltimore, MD 21223	
Lockheed-GA	1
Attn: B. Bradley	
86 S. Cobb Drive, Dept. 72-27	
Marietta, GA 30063	
Marine Corps Air Station (342)	1
Cherry Point, NC 28533-5030	•
cherry rother, no 20000	
Martin Marietta Labs	1
Attn: J. Venables	
1450 S. Rolling Rd.	
Baltimore, Md 21227	
McCloskey Varnish Co.	1
Attn: R. Frusco	
7600 State Rd.	
Phila., PA 19136	
Managara 1 Danielas	1
McDonnel Douglas Attn: B. Williams	4
St. Louis, MO	
Mobay Chemical	1
Attn: B. Sylvester	
Penn-Lincoln Parkway	
West Pittsburg, Pa 15205	
National Bureau of Standards (M. McKnight)	1
Washington, DC 20234	
	,
Naval Air Engineering Center (9321)	1
Lakehurst, NJ 08733-5100	
Naval Air Station (AIRLANT-528)	1
Norfolk, VA 23511-5188	
Naval Air Station, North Island (AIRPAC-7412)	1
San Diego, CA 92135-5100	
Naval Air Systems Command (AIR-41121E, AIR-5304D)	2
Washington, DC 20361	

NADC 87164-60 David Taylor Naval Ship Research & Development Center (2813, 2841) Annapolis. MD 21402-5067 Defense Technical Information Center Cameron Station Alexandria, VA 22314 Deft Inc. Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	2 1 2 1	
(2813, 2841) Annapolis. MD 21402-5067 Defense Technical Information Center Cameron Station Alexandria, VA 22314 Deft Inc. Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1 2	
Defense Technical Information Center Cameron Station Alexandria, VA 22314 Deft Inc. Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
Cameron Station Alexandria, VA 22314 Deft Inc. Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
Alexandria, VA 22314 Deft Inc. Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
Deft Inc. Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
17451 Von Karman Ave. Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	-	
Irvine, CA 92714 Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	-	
Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	-	
Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	-	
1700 S. Mount Prospect Rd. Des Plains, IL 60018 Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1	
Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	•	C)
Haywood, CA 94544		2
		3
		3
Enterprise Chemical	1	
		N N
Wheeling, IL 60090		×
Canaral Dynamics		BUCCOOL NO.
	1	ð
P.O. Box 748		7.
Ft. Worth, TX 76101		8
General Electric	1	3
Attn: P. Lavin	•	<u> </u>
		8
Gruman Aerospace Corp.	1	Ş
		3
		N
	1	3
910 Market St.		
Wilmington, DE 19899		
Bughson Chemicale		3
Attn: A. Patterson	1	7
2000 W. Grandview Blvd.		
Erie, PA 16512		
		42 55 550
		3
		, S
		ă
		F
		þ
	Enterprise Chemical Attn: S. Kish 1191 S. Wheeling Rd. Wheeling, IL 60090 General Dynamics Attn: J. Peoples P.O. Box 748 Ft. Worth, TX 76101 General Electric Attn: P. Lavin Silicone Rd. Waterford, NY 12188 Cruman Aerospace Corp. Attn: G. Kelley Bethpage, NY 11714 Hercules Inc., Coatings Attn: R. Wint 910 Market St. Wilmington, DE 19899 Hughson Chemicals Attn: A. Patterson	31:00 Hayman St. Haywood, CA 94544 Enterprise Chemical Attn: S. Kish 1191 S. Wheeling Rd. Wheeling, IL 60090 General Dynamics Attn: J. Peoples P.O. Box 748 Ft. Worth, TX 76101 General Electric Attn: P. Lavin Silicone Rd. Waterford, NY 12188 Gruman Aerospace Corp. Attn: G. Kelley Bethpage, NY 11714 Hercules Inc., Coatings Attn: R. Wint 910 Market St. Wilmington, DE 19899 Hughson Chemicals Attn: A. Patterson 2000 W. Grandview Blvd. Erie, PA 16512

DISTRIBUTION LIST

	Coples
Advanced Coatings	1
Attn: T. Corboy	•
4343 Temple City Blvd.	
Temple City, CA 91780	
Alox Corp.	1
Attn: D. knowlton	
3943 Buffalo Ave.	
Niagra Falls, NY 14302	
American Cyanamide	1
Attn: J. Bennett	
Bound Brook NJ 08805	
Ameron-Prot. Coat.	1
Attn: F. Farrell	•
201 N. Berry St.	
Brea, CA 92621	
Army Aviation Systems Command (DRDAV-DS)	1
4300 Goodfellow Boulevard	•
St. Louis, MO 63120-1798	
Army Belvoir Research & Development Center (STRBE-VO)	•
Fort Belvoir, VA 22060-5606	1
Army Materials Technology Laboratory (DRXMR-MM)	1
Watertown, MA 02172	
BASF-Wyndot Corp.	1
Attn: M. Nienhuis	
491 Columbia Ave.	
Holland, MI	
Boing Aerospace	1
Attn: W. Hamilton	
P.O. Box 3999	
Seattle, WA 98124	
Bostik Div.	1
Attn: K. Silberger	
20846 S. Normandie Ave.	
Torrance, CA 90502	
Ciba-Geigy Corp.	1
Attn: R. Varron	
Ardsley, NY 10502	

END DATE FILMED DTIC July 88